

Cisco Meraki MR52

Cisco Meraki MR52

Model: Cisco Meraki MR52

Manufacturer: CISCO

Device: Wireless/Networking Business WAP “Wireless Access Point”

Issue: Due to the latest product and drivers not yet being supported, Hydrawise controllers are unable to connect to this wireless access point.

Resolution: You can log into the access point and will need to create a guest SSID. Choose to have a password or not password encrypted, make it a standalone 2.4 g connection, and set a WPA/WPA2 encryption. The controller will now connect to the cloud as it normally should. [Learn More](#) ^[1].